









Assembled Crankshaft
Loctite and Pin then cut out middle of main shaft



Main Shaft
PGMS
1No Req'd



Crank Pin
PGMS
1No Req'd



Crank Web
Steel
2No Req'd

Jowitt Mk 2 Crankshaft	7RevA
Material Steel & PGMS	Scale 1:1